Printed on: 8/30/2009 7:30:46 PM

National Transportation Safety Board	NTSB	ID: ERA09WA1	66	Aircraft Registration Number: PR-SAE				
FACTUAL REPORT	Occuri	ence Date: 02/0	7/2009	Most Critical II	Most Critical Injury: Fatal			
AVIATION	Occuri	ence Type: Accid	dent	Investigated By: Foreign				
Location/Time								
Nearest City/Place	State	Zip Code	Code Local Time		Zone			
Coari			1810	итс				
Airport Proximity: Off Airport/Airstrip	n Landing Facility:	Landing Facility:						
Aircraft Information Summary								
Aircraft Manufacturer	Model/Serie	S		Type of Aircraft				
EMBRAER	EMB110/F	P1		Airplane				
Revenue Sightseeing Flight: No	Air	Air Medical Transport Flight: No						

Narrative

Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:

On February 7, 2009, at 1810 universal time coordinates, an Embraer EMB 110P1, Brazilian registry PT-SEA, operated by Manaus Aerotaxi as a commuter flight, experienced an unknown problem after take-off from the Coari, Amazonas Airport (SWKO) in Coari, Brazil, at 1640. At 1722 the pilot informed approach control at Manaus, Amazonas (SBEG), Eduardo Gomes, Brazil, that he was returning to SWKO, but did not state the reason for that. A witness saw the collision of the airplane with the Manacapuru River, in the Amazon Jungle, and observed the airplane sink right after impact.

The investigation is under the jurisdiction of the Brazilian Authorities, Aeronautical Accident Prevention and Investigation Center. Further information pertaining to this accident may be obtained from:

Chief of Research and Support

Shis - Q1 05 - Vi Comar, Brasilia-DF, Brazil

Phone: 55 61 3364-8824 Facsimile: 55 61 3365-1004

This report is for information purposes only, and contains only information released by or obtained for the Brazilian Government.

Updated on Jun 23 2009 3:00PM

National Transportation Safety Board
FACTUAL REPORT

NTSB ID: ERA09WA166

Occurrence Date: 02/07/2009

AVIATION	lent										
Landing Facility/Approach Information											
Airport Name		Α	Airport ID:	Airpo	rt Elevation	Run	way Used	Runwa	y Lengtl	n Ru	nway Width
Coari, Amazonas	SWKO		131 Ft. MSL	N/A	4						
Runway Surface Type:											
Runway Surface Condition:											
Approach/Arrival Flown: Unknown	own										
VFR Approach/Landing: Unknown	1										
Aircraft Information											
Aircraft Manufacturer EMBRAER			Model/ EMB1	/Series 110/P1					Serial I	Number 52	
Airworthiness Certificate(s): Trans	port							•			
Landing Gear Type: Retractable	- Tricycle										
Amateur Built Acft? No	Certified	d Max (Gross Wt.		12500	LBS	Numbe	r of Engin	es: 2		
Engine Type: Turbo Prop		Engine Manufacturer: Model/Series: PRATT AND WHITNEY PT6A							ated Power: 50 HP		
- Aircraft Inspection Information											
Type of Last Inspection	Date of Last	Pate of Last Inspection Time Since Last Inspection						Airframe	Total Time		
Unknown							urs		Hours		
- Emergency Locator Transmitter (ELT) Information										
ELT Installed?/Type			ELT Operat	ted?		ELT Aid	ded in Locatin	g Accide	ent Site?	ı	
Owner/Operator Information											
Registered Aircraft Owner			Street A	Address	3						
Manaus Aerotaxi	City	City							Zip Code		
Street Address Operator of Aircraft										•	
Manaus Aerotaxi	City							State	Zip Code		
Operator Does Business As: Operator Designator Code:											
- Type of U.S. Certificate(s) Held:											
Air Carrier Operating Certificate(s)	On-demand Air 1	Гахі									
Operating Certificate: Operator Certificate:											
Regulation Flight Conducted Under: Non-U.S., Commercial											
Type of Flight Operation Conducted: Non-scheduled; Domestic; Passenger Only											
	1	FACTI	AL REPO	RT - 4	VIATION						Page 2
]	11010	ALL KLI O	11 - 7	1 1 1/111011						3~ -

National Transportation Safety Board FACTUAL REPORT AVIATION

NTSB ID: ERA09WA166

Occurrence Date: 02/07/2009

	之 製料 图														
AVIATION Occurrence Ty							Accident								
First Pilo	t Information														
Name			City					Sta	te [Date of Birth	Age				
On File															
Sex: M	wn	Certificate Number:													
Certificate(s):															
Airplane Rating(s):															
Rotorcraft/Glider/LTA:															
Instrument	Rating(s):														
Instructor Rating(s):															
Current Bie	nnial Flight Revie	ew?													
Medical Ce	ert.:	Medic	al Cert. St	atus:						Da	te of La	ast Me	edical Ex	kam:	
- Flight Tim	Time Matrix All A/C This Make and Model				Airplane Airplane Single Engine Mult-Engine		Night Instru		Instrument	rument Rotord		Rotorcraft	Glider	Lighter Than Air	
Total Time	Total Time														
Pilot In Cor	ot In Command(PIC)										\perp				
Instructor	uctor		\dashv								\perp				
Instruction	Received		<u> </u>	\dashv											
Last 90 Da	Last 90 Days											\perp			
Last 30 Da	-			+								+			
Last 24 Ho		<u> </u>	<u> </u>	Щ.				Τ					Τ.		
Seatbelt Us	sed? Yes	Shou	ulder Harn	iess U	Jsed? Yes			Toxico	ology Pe	rformed	?		Se	cond Pilot?	
Flight Plan/Itinerary															
Type of Flig	ght Plan Filed: Uı	nknown													
Departure I	Point							State		Airport	dentifie	r	Departure Time		Time Zone
Coari										SWKO			1640 UTC		UTC
Destination	1							State		Airport	dentifie	er			
Eduardo				SBEG											
Type of Clearance: Unknown															
Type of Airspace:															
Weather	Information														
Source of	Wx Information:		· · ·												
				F	FACTUAL	REPORT -	- AV	IATION	٧						Page 3

National Transportation Safety Board FACTUAL REPORT

NTSB ID: ERA09WA166

Occurrence Date: 02/07/2009

	AVIATION	0	Occurrence Type: Accident									
Weather	Information							•				
WOF ID	Observation Time	Time Zone	WOF	Elevation	on WOF Distance From Accident S					Direction From Accident Site		
										Deg. Mag.		
			Ft. MSL					NM	NM I			
Sky/Lowes	st Cloud Condition:			Ft. AGL					Condition of Light:			
Lowest Ce	eiling:		Ft. AGL		Visibili	ty:	SM	Alt	imeter: "Hg			
Temperatu	ıre: °C		°C We									
Wind Direc	ction:	Wind Sp	peed:			Wind	Gusts:					
Visibility (F	RVR): Ft.	Visibility	y (RVV)	SM	T							
Precip and	d/or Obscuration:											
Accident	Information											
Aircraft Da	mage: Destroyed	Air	Aircraft Fire: None					xplosic	on			
			·									
- Injury Su	mmary Matrix	Fatal	Serious	Minor	Non	ne	TOTAL					
First Pi	ilot	1					1					
Second	d Pilot	1					1					
Studer	nt Pilot											
Flight I	nstructor											
Check	Pilot											
Flight E	Engineer											
Cabin /	Attendants											
Other (Crew											
Passer	ngers	22		4			26					
- TOTAL A	ABOARD -	24		4			28					
Other (Ground											
- GRAND TOTAL - 24 4 28												

National Transportation Safety Board

NTSB ID: ERA09WA166

FACTUAL REPORT	Occurrence Date: 02/07/2009	
AVIATION	Occurrence Type: Accident	
Administrative Information		
Investigator-In-Charge (IIC)		
Ralph L. Wilson		
Additional Persons Participating in This Accident/Incide	ent Investigation:	